EP

Example Pest Co

Licence NSW 000000 · ABN 00 000 000 000
0400 000 000 · office@example.com

TREATMENT CERTIFICATE
13 November 2026

TERMITE MANAGEMENT

Treatment Certificate

CLIENT
Sam Taylor

PROPERTY ADDRESS
7 Banksia Drive, Epping NSW 2121

CERTIFICATE NO.
TC-20261113-9499

TREATMENT DATE
13 November 2026, 8:30 am to 12:00 pm

TECHNICIAN
Alex Example

LICENCE NO.
NSW 000000

TREATMENT CARRIED OUT

TARGET PEST
Subterranean termites

EQUIPMENT
Low-pressure sprayer, trenching tools

WEATHER
Fine and dry

- Direct treatment of active termite workings

AREAS TREATED
Backyard gum tree; perimeter of the house

AREAS NOT TREATED
Back section of the subfloor (stored items)

SYSTEM INSTALLED
Termite baiting system installed, 8 stations

WHERE IT WAS INSTALLED
Perimeter of the house

PRODUCTS APPLIED

PRODUCT	APPLICATION RATE	QUANTITY	BATCH NO.
Termidor Foam fipronil	As per label	2 cans	B-0000

DURABLE NOTICE

SYSTEM
Termite baiting system installed

DATE INSTALLED
13 November 2026

FUTURE INSPECTIONS
First by 13 February 2027, then at least every 12 months

INSTALLED BY
Example Pest Co
Alex Example, licence NSW 000000

NOTICE
New durable notice placed: meter box

KEEPING THE PROPERTY PROTECTED

1. Safety and re-entry: Keep garden beds below the slab edge and away from the bait stations.
2. The bait stations need checking as often as the manufacturer directs. Do not move, cover or remove them.
3. Book your next timber pest inspection by 13 February 2027. AS 3660.2 recommends one at least every 12 months.
4. Keep weep holes clear and leaks fixed, and call us if you see termites or mud leads.

Alex Example
TECHNICIAN · LICENCE NSW 000000

SIGNATURE

13 November 2026
DATE

The treatment above was carried out, and the system installed, by this technician in line with the manufacturer's directions, the product label and AS 3660.2. Neither repairs existing damage, and no treatment or system can guarantee termites will never return. Regular inspections are the best protection.